



WARP Simulations Update

Topics:


- What has been done?
 - Particle Extraction
 - Fast particle mover
 - Linear setup
- Problems
 - Over bending in turn
- To be done
 - Bend correction
 - Windows
 - Decision of which data to extract
 - Restart procedure guide

TEL2 setup










- 58 degrees bends
- 3 solenoids in bends
- New syslength 4.68m


Bend only changes lattice if top.diposet correct

Last stance











Particle Extraction



```
ff = open('../Results/'+date+'/'+machine_type+"_"+date+time+"_"+machine_injtype+"_'
for x,y,z in zip(elec.xp,elec.yp,elec.zp):
   ff.write('%10.5e %10.5e %10.5e\n' %(x,y,z))
ff.close()
```



```
-4.54500e-03 -3.22979e-04 8.06582e-01
1.34445e-03 -4.56397e-03 7.86045e-01
-3.37691e-03 -1.38237e-03 7.84744e-01
3.08474e-04 -3.77889e-03 8.03647e-01
3.97100e-03 2.36444e-03 7.96436e-01
2.23096e-03 4.03463e-03 8.11527e-01
1.15403e-04 6.04984e-03 6.24550e-01
```

- Cleanup necessary Text information
- File size = 120 kb
- List of all extractable information necessary
- Plottable in other tools (3D Plots?)



Fast Particle Mover




w3d.interpdk[1]=1
w3d.igradb=1
from loadgradb import setbsqgrad
setbsqgrad(w3d.nx,w3d.ny,w3d.nz,w3d.xmmin,w3d.xmmax,w3d.ymmin,w3d.ymmax,w3d.zmmin,w3d.zmmax)

- At least 50 times less timesteps -
- Can simulate 1.5 m on my local desktop at LHC magnet settings
- Install WARP on vdisk 1 -> 100%?









Bend issues – TEL2 settings









0.00

-0.05

-0.03-0.02-0.01 0.00 0.01

×

ı_{_700} **0.00** ŀ

400₹

z window0 = 0.0000e+00, 2.0000e+00

-0.02

0.00

Settings:

Bmain=5, Bcoll=0.43, Bbend=Bcoll/9.35


Cathode Voltage: 500V




Bend issues – TEL2 settings









z window0 = 0.0000e+00, 2.0000e+00



Bmain=5, Bcoll=0.43, Bbend=Bcoll Cathode Voltage: 500V


What to do about bends?



Linear TEL2 setup








Settings: Bmain=5.

Bmain=5, Bcoll=0.43, Bbend=Bcoll

Cathode Voltage: 500V

Is the whole good enough?





Next steps



- Install WARP on vdisk1 and check if powerfull enough
- Figure out bend issues -> Plot magnetic field along simulation
- Implement window and plot limits for center of interaction region to study hole
- Write dump & restart instructions
- Plot particle export data
- Run a set of sample simulations for LHC, TEL2 and tbench parameters. -> focus on gun injection



ADMIN rights on vdisk1?

